



6.0 Project Photos



Main entry corridor post-demolition




Future recreation office space – wall removed to open up the area, demolition complete

6.0 Project Photos




South end future
community hall room
post-demolition

North end future
community hall room
post-demolition



6.0 Project Photos



Future childcare space post-demolition

Future kitchen space post-demolition

